



Envirolok, LLC | www.envirolok.com | ecosolutions@envirolok.com 10101 N Casey Road Evansville, WI 53536 | 608.226.2565













Envirolok, LLC | www.envirolok.com | ecosolutions@envirolok.com 10101 N Casey Road Evansville, WI 53536 | 608.226.2565



## **SANDY RIVER** - Riverbank Restoration

Year Constructed 2011

**Client**Private Homeowners

Reinforcement Geogrid

**Vegetation**Live Stakes, Plant Plugs
Hydroseed

Engineer Robert Race, P.E. Envirolok Consulting Engineer

Project Partners
Sunmark Environmental
Services, LLC

NorthWest Hydro-Mulchers

## + Project Snapshot

During a high flooding event, the riverbank beneath this home began to collapse and wash away. This needed to be stabilized as soon as possible and required a fully engineered, stable solution that would prevent this from happening in the future. Envirolok was chosen because it could provide the solution needed and permits were received within 10 days of the incident. For construction, they cut into the existing bank above the water's edge and placed a hard armor of large boulders and rootwads to help absorb and deflect incoming energy from the river. This stabilized the toe of the slope and the Envirolok units were built up the slope. Geogrid was wrapped around the Envirolok bags and embedded into the riverbank to provide sheer strength. The entire slope was then planted with over 800 native plant stakes, plugs, and hydroseeded to create dense vegetation that would further bind the system to the parent material. Envirolok was able to stabilize the slope, prevent further erosion, and was a quick easy solution to a disastrous event.





## CANOE BAY, COLUMBIA RIVER - Riverbank Restoration

Year Constructed 2013

Project Size 11,000 sf

Client
Private/City of Portland

Reinforcement
Earth Anchors

**Vegetation**Plant Plugs

Engineer
Robert Race, P.E.
Envirolok Consulting Engineer

## + Project Snapshot

Prior to the current owner, the project site was used as a dumping ground of various construction materials. Many of these materials were dumped along the river's edge as a means of protecting the bank. High water levels and routine flood conditions continually damaged and began to erode the banks. The property owner worked with the City to look at bank repair options, but found extreme levels of contaminants along the riverbank soils and in the water. In order to complete improvements to the boatyard and marina, the property owner was required to cap and remediate the site at the riverbank. Envirolok was recommended for it's ability to create a reinforced and vegetative solution that could also limit contaminates from reaching the waterway. In addition to sealing the contaminated soils, Envirolok could withstand the tidal influences and flood conditions. To reinforce the Envirolok system, earth anchors were used and vegetation flourished, adding additional strength and support. Envirolok successfully remediated this site and created a lasting solution for this eroding riverbank.

